



Foot button, by pressing it, sends to scale commands TARE or PRINT (print weighing result).

It allows for performance of complex procedures for weighing, filling and dosing with two hands involved in this procedure, and simultaneous tarring, printing and sending the result to computer. Proper cooperation of the system: scale – computer – PRINT button – TARE button; is provided by signal distributor also included in the set of buttons.

Set of TARE or PRINT buttons is applicable for laboratory weighing instrument by RADWAG equipped with graphic display and RADWAG industrial scales applying indicators or terminals series: TMC and HX.

