

Last Updated 6-11-09

| Alpha Number  | LECO Number | Buehler Number |
|---------------|-------------|----------------|
| <u>AM0001</u> | 810-001     | 16-5200        |
| <u>AM0002</u> | 810-002     | 16-5200        |
| <u>AM0003</u> | 810-003     | 16-5200        |
| <u>AM0004</u> | 810-004     | 16-5200        |
| <u>AM0005</u> | 810-005     | 16-5200        |
| <u>AM0006</u> | 810-006     | 16-5200        |
| <u>AM0007</u> | 810-007     | 16-5200        |
| <u>AM0008</u> | 810-008     |                |
| <u>AM0009</u> |             |                |
| <u>AM0020</u> |             |                |
| <u>AM0021</u> | 810-021     |                |
| <u>AM0022</u> | 810-022     |                |
| <u>AM0023</u> | 810-023     |                |
| <u>AM0024</u> | 810-024     |                |
| <u>AM0025</u> | 810-025     |                |
| <u>AM0033</u> | 810-033     | 30-5528        |
| <u>AM0034</u> | 810-034     | 30-5228        |
| <u>AM0035</u> | 810-035     | 30-5538        |
| <u>AM0036</u> | 810-036     | 30-5538        |
| <u>AM0085</u> | 810-085     |                |
| <u>AM0086</u> | 810-086     |                |
| <u>AM0087</u> | 810-087     |                |
| <u>AM0088</u> | 810-088     | 30-5243        |
| <u>AM0089</u> | 810-089     | 30-5243        |
| <u>AM0090</u> | 810-090     | 30-5243        |
| <u>AM0091</u> | 810-091     | 30-5243        |
| <u>AM0160</u> |             |                |
| <u>AM0161</u> | 810-161     | 30-5160        |
| <u>AM0162</u> | 810-162     | 30-5160        |
| <u>AM0163</u> | 810-163     | 30-5160        |
| <u>AM0164</u> | 810-164     | 30-5160        |
| <u>AM0166</u> |             |                |
| <u>AM0167</u> |             |                |

|               |         |         |
|---------------|---------|---------|
| <u>AM0168</u> |         |         |
| <u>AM0169</u> |         |         |
| <u>AM0200</u> | 820-200 |         |
| <u>AM0217</u> |         |         |
| <u>AM0218</u> |         |         |
| <u>AM0219</u> | 810-219 | 30-5108 |
| <u>AM0221</u> | 810-221 | 30-5108 |
| <u>AM0223</u> | 810-223 | 30-5108 |
| <u>AM0225</u> | 810-225 | 30-5108 |
| <u>AM0227</u> | 810-227 | 30-5108 |
| <u>AM0229</u> | 810-229 | 30-5108 |
| <u>AM0231</u> | 810-231 |         |
| <u>AM0232</u> |         |         |
| <u>AM0233</u> | 810-223 | 30-5138 |
| <u>AM0235</u> | 810-235 | 30-5138 |
| <u>AM0237</u> | 810-237 | 30-5138 |
| <u>AM0239</u> | 810-239 | 30-5138 |
| <u>AM0241</u> | 810-241 | 30-5138 |
| <u>AM0242</u> |         |         |
| <u>AM0243</u> | 810-243 | 30-5138 |
| <u>AM0244</u> |         |         |
| <u>AM0245</u> | 810-245 | 15-5112 |
| <u>AM0247</u> | 810-247 | 15-5112 |
| <u>AM0249</u> | 810-249 | 15-5112 |
| <u>AM0251</u> | 810-251 | 15-5112 |
| <u>AM0253</u> | 810-253 | 15-5112 |
| <u>AM0255</u> | 810-255 | 15-5112 |
| <u>AM0256</u> | 810-257 | 15-5112 |
| <u>AM0257</u> |         |         |
| <u>AM0258</u> |         |         |
| <u>AM0259</u> | 810-259 | 30-5118 |
| <u>AM0261</u> | 810-261 | 30-5118 |
| <u>AM0263</u> | 810-263 | 30-5118 |
| <u>AM0265</u> | 810-265 | 30-3118 |
| <u>AM0267</u> | 810-267 | 30-5118 |

|                 |         |         |
|-----------------|---------|---------|
| <u>AM0269</u>   | 810-269 | 30-5118 |
| <u>AM0270</u>   |         |         |
| <u>AM0271</u>   | 810-271 | 30-5148 |
| <u>AM0273</u>   | 810-273 | 30-5148 |
| <u>AM0275</u>   | 810-275 | 30-5148 |
| <u>AM0277</u>   | 810-277 | 30-5148 |
| <u>AM0279</u>   | 810-279 | 30-5148 |
| <u>AM0281</u>   | 810-281 | 30-5148 |
| <u>AM0283</u>   |         |         |
| <u>AM0284</u>   |         |         |
| <u>AM0309</u>   |         | 10-4127 |
| <u>AM0311</u>   |         |         |
| <u>AM0316</u>   | 810-316 |         |
| <u>AM0317</u>   |         |         |
| <u>AM0327</u>   | 810-327 | 40-7224 |
| <u>AM0328</u>   | 810-328 |         |
| <u>AM0332</u>   | 810-332 |         |
| <u>AM0333</u>   | 810-330 | 40-7074 |
| <u>AM0334</u>   | 810-334 |         |
| <u>AM0341</u>   | 812-021 |         |
| <u>AM0341PB</u> |         |         |
| <u>AM0342</u>   | 812-024 |         |
| <u>AM0342PB</u> |         |         |
| <u>AM0343</u>   |         |         |
| <u>AM0343PB</u> |         |         |
| <u>AM0344</u>   |         |         |
| <u>AM0344PB</u> |         |         |
| AM0351          |         |         |
| AM0352          |         |         |
| <u>AM0357</u>   | 812-045 | 15-5132 |
| <u>AM0358</u>   | 812-046 | 15-5132 |
| <u>AM0396</u>   | 810-396 | 40-4649 |
| <u>AM0397</u>   | 810-397 | 40-4659 |
| <u>AM0398</u>   | 810-398 | 40-4669 |
| <u>AM0399</u>   | 810-399 | 40-4679 |

|               |         |         |
|---------------|---------|---------|
| <u>AM0401</u> | 810-401 | 40-4689 |
| <u>AM0402</u> | 810-402 | 60-4548 |
| <u>AM0403</u> | 810-403 | 60-4558 |
| <u>AM0404</u> | 810-404 | 60-4568 |
| <u>AM0405</u> | 810-405 | 60-4578 |
| <u>AM0406</u> | 810-406 | 60-4588 |
| <u>AM0424</u> |         | 30-5114 |
| <u>AM0425</u> | 810-446 | 30-5114 |
| <u>AM0426</u> | 810-425 | 30-5114 |
| <u>AM0427</u> | 810-426 | 30-5114 |
| <u>AM0428</u> | 810-427 | 30-5114 |
| <u>AM0429</u> | 810-428 | 30-5114 |
| <u>AM0430</u> | 810-429 | 30-5114 |
| <u>AM0436</u> | 810-430 |         |
| <u>AM0437</u> | 810-437 |         |
| <u>AM0438</u> |         |         |
| <u>AM0445</u> | 810-545 |         |
| <u>AM0446</u> | 810-546 |         |
| <u>AM0447</u> | 810-547 |         |
| <u>AM0451</u> | 810-645 | 40-7072 |
| <u>AM0452</u> |         |         |
| <u>AM0459</u> |         |         |
| <u>AM0460</u> | 810-515 |         |
| <u>AM0461</u> | 810-461 | 40-7008 |
| <u>AM0462</u> | 810-462 | 40-7058 |
| <u>AM0463</u> | 810-648 | 40-7068 |
| <u>AM0464</u> |         | 40-7078 |
| <u>AM0465</u> | 810-465 | 40-7308 |
| <u>AM0466</u> | 810-466 |         |
| <u>AM0467</u> | 810-315 |         |
| <u>AM0468</u> | 810-461 |         |
| <u>AM0469</u> | 810-469 |         |
| <u>AM0471</u> | 810-463 |         |
| <u>AM0472</u> | 810-467 | 40-7408 |
| <u>AM0482</u> | 810-482 |         |

|               |         |         |
|---------------|---------|---------|
| <u>AM0485</u> | 810-485 | 20-4000 |
| <u>AM0486</u> | 810-815 | 20-4100 |
| <u>AM0495</u> | 810-495 |         |
| <u>AM0496</u> | 810-491 |         |
| <u>AM0497</u> | 810-497 | 40-7218 |
| <u>AM0500</u> | 810-945 | 40-6629 |
| <u>AM0501</u> |         |         |
| <u>AM0502</u> | 810-944 | 40-6630 |
| <u>AM0503</u> | 810-943 | 40-6631 |
| <u>AM0504</u> | 810-942 | 40-6632 |
| <u>AM0505</u> | 810-941 | 40-6633 |
| <u>AM0506</u> | 810-940 | 40-6634 |
| <u>AM0507</u> | 810-939 | 40-6635 |
| <u>AM0508</u> | 810-938 | 40-6636 |
| <u>AM0510</u> | 810-510 |         |
| <u>AM0511</u> | 810-511 | 40-7062 |
| <u>AM0512</u> | 810-512 |         |
| <u>AM0514</u> | 810-514 | 40-7132 |
| <u>AM0515</u> |         |         |
| <u>AM0516</u> | 810-516 |         |
| <u>AM0517</u> | 810-333 |         |
| <u>AM0518</u> | 810-518 |         |
| <u>AM0519</u> |         |         |
| <u>AM0529</u> | 810-529 |         |
| <u>AM0538</u> | 810-498 | 40-7228 |
| <u>AM0539</u> | 810-520 | 40-7242 |
| <u>AM0540</u> | 810-543 | 40-7222 |
| <u>AM0541</u> |         |         |
| <u>AM0542</u> |         |         |
| <u>AM0544</u> |         |         |
| <u>AM0545</u> | 810-487 | 16-5400 |
| <u>AM0546</u> | 810-499 | 16-5400 |
| <u>AM0547</u> | 810-489 | 16-5400 |
| <u>AM0548</u> | 810-493 | 16-5400 |
| <u>AM0549</u> | 810-470 | 40-7208 |

AM0550

AM0551

AM0552

AM0553

AM0554

AM0635                      800-635                                      20-3040

AM0644                      810-644

AM0647                      810-647

AM0665                      810-665                                      40-6365

AM0701

AM0702

AM0703

AM0704

AM0705

AM0706

AM0707

AM0708

AM0709

AM0713

AM0717

AM0719

AM0721

AM0722

AM0723

AM0724

AM0725

AM0726

AM0727

AM0728

AM0729

AM0730

AM0731

AM0732

AM0778                      810-778                                      40-6325

AM0779                      810-779                                      40-6325

|                |         |         |
|----------------|---------|---------|
| <u>AM0782</u>  | 810-782 | 40-6323 |
| <u>AM0783</u>  | 810-783 | 40-6323 |
| <u>AM0786</u>  | 810-786 | 40-6321 |
| <u>AM0787</u>  | 810-787 | 40-6321 |
| <u>AM0788</u>  | 810-788 |         |
| <u>AM0818</u>  | 810-818 | 40-6361 |
| <u>AM0825</u>  | 810-825 | 40-6360 |
| <u>AM0825G</u> | 810-825 | 40-6360 |
| <u>AM0826</u>  | 810-826 | 40-6365 |
| <u>AM0827</u>  | 810-827 | 40-6363 |
| <u>AM0828</u>  | 810-828 |         |
| <u>AM0829</u>  | 810-829 |         |
| <u>AM0830</u>  | 810-830 |         |
| <u>AM0831</u>  | 810-831 |         |
| <u>AM0832</u>  | 810-819 | 40-6361 |
| <u>AM0833</u>  |         |         |
| <u>AM0834</u>  | 810-832 | 40-6363 |
| <u>AM0835</u>  |         |         |
| <u>AM0858</u>  | 810-858 | 30-5532 |
| <u>AM0859</u>  | 810-859 | 30-5532 |
| <u>AM0865</u>  | 810-865 | 40-6241 |
| <u>AM0866</u>  | 810-866 | 40-6240 |
| <u>AM0867</u>  | 810-867 |         |
| <u>AM0868</u>  | 810-868 |         |
| <u>AM0875</u>  |         | 40-6192 |
| <u>AM0876</u>  |         | 40-6181 |
| <u>AM0877</u>  |         | 40-6212 |
| <u>AM0878</u>  |         | 40-6202 |
| <u>AM0885</u>  | 810-885 |         |
| <u>AM0886</u>  | 810-886 |         |
| <u>AM0887</u>  | 810-869 | 40-6244 |
| <u>AM0888</u>  | 810-870 | 40-6243 |
| <u>AM0889</u>  | 810-871 | 40-6247 |
| <u>AM0890</u>  | 810-872 | 40-6246 |
| <u>AM0891</u>  | 810-873 | 40-6250 |

|                |         |         |
|----------------|---------|---------|
| <u>AM0892</u>  | 810-874 | 40-6249 |
| <u>AM0893</u>  | 810-912 | 40-6453 |
| <u>AM0894</u>  | 810-913 | 40-6252 |
| <u>AM0895</u>  | 810-914 | 40-6255 |
| <u>AM0896</u>  | 810-915 |         |
| <u>AM0897</u>  |         |         |
| <u>AM0898</u>  | 810-880 | 40-6258 |
| <u>AM0899</u>  | 810-881 |         |
| <u>AM0901</u>  | 810-882 | 40-6259 |
| <u>AM0906</u>  |         | 40-6138 |
| <u>AM0907</u>  |         | 40-6128 |
| <u>AM0908</u>  |         | 40-6152 |
| <u>AM0909</u>  |         | 40-6142 |
| <u>AM0910</u>  |         | 40-6172 |
| <u>AM0911</u>  |         | 40-6162 |
| <u>AM0916</u>  |         |         |
| <u>AM0917</u>  |         |         |
| <u>AM0918</u>  |         |         |
| <u>AM0919</u>  |         |         |
| <u>AM0995</u>  | 813-090 |         |
| <u>AM0996</u>  |         | 60-3255 |
| <u>AM1002</u>  | 811-002 | 40-6016 |
| <u>AM1003</u>  | 811-003 | 40-6032 |
| <u>AM1004</u>  | 811-04  | 40-6064 |
| <u>AM1006</u>  | 811-002 | 40-6016 |
| <u>AM1007</u>  | 811-003 | 40-6032 |
| <u>AM1008</u>  | 811-004 | 40-6064 |
| <u>AM1010</u>  | 810-998 | 40-6530 |
| <u>AM1012</u>  | 810-997 | 40-6531 |
| <u>AM1014</u>  | 810-996 | 40-6532 |
| <u>AM1016</u>  | 810-995 | 40-6533 |
| <u>AM1018</u>  | 810-994 | 40-6534 |
| <u>AM1020</u>  |         |         |
| <u>AM1022</u>  | 812-110 | 40-6370 |
| <u>AM1022S</u> | 812-121 | 40-6370 |



|               |         |         |
|---------------|---------|---------|
| <u>AM1023</u> | 811-023 | 11-1193 |
| <u>AM1024</u> | 811-024 | 11-1193 |
| <u>AM1031</u> |         | 40-3200 |
| <u>AM1035</u> | 811-035 | 10-4110 |
| <u>AM1036</u> | 811-037 | 10-4112 |
| <u>AM1037</u> | 811-043 | 10-4116 |
| <u>AM1049</u> | 811-049 | 10-4120 |
| <u>AM1050</u> | 811-061 |         |
| <u>AM1051</u> | 811-073 | 10-4220 |
| <u>AM1052</u> | 811-053 | 10-4140 |
| <u>AM1053</u> | 811-053 | 10-4145 |
| <u>AM1059</u> | 811-059 | 10-4210 |
| <u>AM1061</u> | 811-059 | 10-4212 |
| <u>AM1065</u> | 811-065 | 10-4410 |
| <u>AM1066</u> | 811-102 | 10-4440 |
| <u>AM1067</u> | 811-067 | 10-4216 |
| <u>AM1080</u> |         | 10-4427 |
| <u>AM1081</u> | 811-081 | 10-4412 |
| <u>AM1083</u> | 811-083 |         |
| <u>AM1089</u> | 811-089 | 10-4416 |
| <u>AM1095</u> | 811-095 | 10-4420 |
| <u>AM1103</u> |         |         |
| <u>AM1104</u> | 811-104 | 10-4445 |
| <u>AM1105</u> |         |         |
| <u>AM1106</u> |         |         |
| <u>AM1107</u> |         |         |
| <u>AM1108</u> | 811-108 | 10-3330 |
| <u>AM1109</u> | 811-109 | 10-3330 |
| <u>AM1110</u> | 810-697 | 75-6000 |
| <u>AM1111</u> | 811-111 | 20-3100 |
| <u>AM1118</u> | 811-118 | 20-3200 |
| <u>AM1123</u> | 811-123 | 20-3300 |
| <u>AM1128</u> | 811-128 |         |
| <u>AM1133</u> | 811-133 | 20-3400 |
| <u>AM1135</u> | 811-135 |         |

|               |         |         |
|---------------|---------|---------|
| <u>AM1136</u> |         |         |
| <u>AM1137</u> | 810-137 | 11-4264 |
| <u>AM1138</u> |         | 11-4263 |
| <u>AM1140</u> |         |         |
| <u>AM1142</u> | 811-037 |         |
| <u>AM1144</u> |         |         |
| <u>AM1145</u> |         |         |
| <u>AM1146</u> | 811-146 |         |
| <u>AM1147</u> |         |         |
| <u>AM1161</u> | 811-563 |         |
| <u>AM1162</u> | 811-563 |         |
| <u>AM1163</u> | 811-563 | 20-8130 |
| <u>AM1164</u> | 811-563 | 20-8130 |
| <u>AM1165</u> | 811-563 | 20-8132 |
| <u>AM1166</u> |         |         |
| <u>AM1167</u> | 811-563 |         |
| <u>AM1168</u> | 811-563 |         |
| <u>AM1169</u> | 811-563 | 20-8136 |
| <u>AM1170</u> | 811-563 | 20-8138 |
| <u>AM1201</u> | 811-201 | 20-3560 |
| <u>AM1202</u> | 811-202 | 20-3562 |
| <u>AM1203</u> | 811-203 | 20-3564 |
| <u>AM1204</u> |         |         |
| <u>AM1205</u> |         | 20-3568 |
| <u>AM1206</u> |         | 20-3566 |
| <u>AM1207</u> |         |         |
| <u>AM1208</u> |         |         |
| <u>AM1209</u> |         |         |
| <u>AM1271</u> | 811-271 | 20-3046 |
| <u>AM1275</u> | 811-275 | 20-8177 |
| <u>AM1279</u> | 811-279 |         |
| <u>AM1300</u> |         |         |
| <u>AM1301</u> | 811-301 | 20-3111 |
| <u>AM1302</u> | 81-302  | 20-3111 |
| <u>AM1303</u> | 811-303 |         |

|               |         |         |
|---------------|---------|---------|
| <u>AM1304</u> |         |         |
| <u>AM1305</u> | 811-305 | 20-3112 |
| <u>AM1306</u> | 811-306 | 20-3112 |
| <u>AM1307</u> | 811-307 |         |
| <u>AM1308</u> |         |         |
| <u>AM1309</u> | 811-309 | 20-3113 |
| <u>AM1310</u> | 811-310 | 20-3113 |
| <u>AM1311</u> | 811-311 |         |
| <u>AM1312</u> |         |         |
| <u>AM1313</u> | 811-313 | 20-3211 |
| <u>AM1314</u> | 811-314 | 20-3211 |
| <u>AM1315</u> | 811-315 |         |
| <u>AM1316</u> |         |         |
| <u>AM1317</u> | 811-317 | 20-3212 |
| <u>AM1318</u> | 811-318 | 20-3212 |
| <u>AM1319</u> | 811-319 |         |
| <u>AM1320</u> |         |         |
| <u>AM1321</u> | 811-321 | 20-3213 |
| <u>AM1322</u> | 811-322 | 20-3213 |
| <u>AM1323</u> | 811-323 |         |
| <u>AM1324</u> |         |         |
| <u>AM1325</u> | 811-325 | 20-3311 |
| <u>AM1326</u> | 811-326 | 20-3311 |
| <u>AM1327</u> | 811-327 |         |
| <u>AM1328</u> |         |         |
| <u>AM1329</u> | 811-329 | 20-3312 |
| <u>AM1330</u> | 811-330 | 20-3312 |
| <u>AM1331</u> | 811-331 |         |
| <u>AM1332</u> |         |         |
| <u>AM1333</u> | 811-333 | 20-3313 |
| <u>AM1334</u> | 811-334 | 20-3313 |
| <u>AM1335</u> | 811-335 |         |
| <u>AM1500</u> |         | 69-3173 |
| <u>AM1501</u> |         | 69-3172 |
| <u>AM1502</u> |         |         |

|               |         |         |
|---------------|---------|---------|
| <u>AM1503</u> |         | 69-3171 |
| <u>AM1504</u> |         | 69-3170 |
| <u>AM1510</u> |         |         |
| <u>AM1511</u> |         |         |
| <u>AM1512</u> |         |         |
| <u>AM1513</u> |         |         |
| <u>AM1514</u> |         |         |
| <u>AM1634</u> | 811-634 | 30-7508 |
| <u>AM1635</u> | 811-635 | 30-7512 |
| <u>AM1636</u> |         | 30-7510 |
| <u>AM1724</u> | 801-724 | 11-2490 |
| <u>AM1725</u> |         | 10-4000 |
| <u>AM1801</u> |         | 15-6830 |
| <u>AM1802</u> |         | 15-6815 |
| <u>AM1803</u> |         | 15-6809 |
| <u>AM1804</u> |         | 15-6806 |
| <u>AM1805</u> |         | 15-6803 |
| <u>AM1806</u> |         | 15-6801 |
| <u>AM1807</u> |         | 15-6795 |
| <u>AM1811</u> |         |         |
| <u>AM1812</u> |         |         |
| <u>AM1813</u> |         |         |
| <u>AM1814</u> |         |         |
| <u>AM1815</u> |         |         |
| <u>AM1816</u> |         |         |
| <u>AM1817</u> |         |         |
| <u>AM2080</u> |         |         |
| <u>AM2081</u> |         |         |
| <u>AM2082</u> |         |         |
| <u>AM2083</u> |         |         |
| <u>AM2084</u> |         |         |
| <u>AM2085</u> |         |         |
| <u>AM2086</u> |         |         |
| <u>AM2087</u> |         |         |
| <u>AM2090</u> | 812-202 |         |

|               |         |         |
|---------------|---------|---------|
| <u>AM2091</u> | 812-204 | 30-5125 |
| <u>AM2092</u> | 812-206 | 30-5125 |
| <u>AM2093</u> |         |         |
| <u>AM2093</u> | 812-208 | 30-5125 |
| <u>AM2094</u> |         |         |
| <u>AM2095</u> | 812-212 | 30-5125 |
| <u>AM2096</u> | 812-214 | 30-5125 |
| <u>AM2097</u> | 812-218 | 30-5125 |
| <u>AM2098</u> | 812-220 | 30-5125 |
| <u>AM2099</u> |         |         |
| <u>AM2100</u> | 810-291 | 30-5121 |
| <u>AM2101</u> |         |         |
| <u>AM2102</u> | 810-292 | 30-5121 |
| <u>AM2103</u> | 810-293 | 30-5121 |
| <u>AM2104</u> | 810-294 | 30-5121 |
| <u>AM2105</u> | 810-295 | 30-5121 |
| <u>AM2106</u> | 810-296 | 30-5121 |
| <u>AM2107</u> | 810-297 | 30-5121 |
| <u>AM2108</u> | 810-856 | 30-5542 |
| <u>AM2109</u> | 810-857 | 30-5542 |
| <u>AM2120</u> | 812-201 | 30-5125 |
| <u>AM2121</u> |         |         |
| <u>AM2122</u> | 812-203 | 30-5125 |
| <u>AM2123</u> | 812-205 | 30-5125 |
| <u>AM2124</u> | 812-207 | 30-5125 |
| <u>AM2125</u> | 812-209 | 30-5125 |
| <u>AM2126</u> | 812-211 | 30-5125 |
| <u>AM2127</u> | 812-213 | 30-5125 |
| <u>AM2128</u> | 812-217 | 30-5125 |
| <u>AM2129</u> | 812-219 | 30-5125 |
| <u>AM3018</u> | 810-990 | 20-8181 |
| <u>AM3019</u> | 810-991 | 20-8182 |
| <u>AM3020</u> | 810-992 | 20-8183 |
| <u>AM4025</u> |         |         |
| <u>AM7052</u> |         | 40-7052 |

AM7212

40-7212

AM7602